

Ref.	Elevation	Level	Condition: Head	Priority	Cost £	Condition: Cill	Priority	Cost £
W01	Front	Ground	To the head there is a slight hair line crack.	3		The bottom cill shows signs of chipping, and historic localised repair on the bottom left-hand side	3	
W02	Front	Ground	To the head there are slight hair line cracks.	2		The bottom has multiple larger cracks, which are roughly 5mm in width in places.	2	
W03	Front	Ground	There is evidence of an historic repair, and an open joint to a section of the string course. There is a slight hairline crack to the head.	2		There are 2 nr. hairline cracks to the bottom cill.	2	
W04	Front	Ground	There is some hairline cracking to the stringcourse, above the head.	3		No cill.	3	
W05	Front	Ground	There is 1 nr. hairline crack to the head.	3		There are 2 nr. cracks to the cill, which are slightly wider than hairline cracking	3	
W06	Front	Ground	There is 1 nr. hairline crack to the head.	3		There is 1 nr. hairline crack to the cill	3	
W07	Front	Ground	Unable to inspect.			Unable to inspect.		
W08	Front	Ground	Unable to inspect.			Unable to inspect.		
W09	Front	Ground	Unable to inspect.			Unable to inspect.		
W10	Front	Ground	Fair condition. Only very small hairline crack.	3		Unable to inspect.	3	
W11	Front	First	Flush to the soffit.	2		There has been an historic repair to the cill. In fair condition, with some evidence of fissuring.	2	
W12	Front	First	Fair condition.	1		There has been an historic repair, and decoration to the cill. It is in poor condition, with the render and paint blistering.	1	
W13	Front	First	There is a hairline crack to the head. There is some misalignment with two sections of the string course	2		There has been an historic repair to the cill. Fair condition, but has been decorated white, and is starting to crack.	2	
W14	Front	First	There is some hairline cracking to the three sections of stringcourse, above the head.	3		No cill.	3	
W15	Front	First	There is a hairline crack to the head. With some evidence of isolated repairs.	3		The cill has been repaired and decorated historically. There is evidence of cracking, the colour matching on the render is not uniform with the rest of the building. There are also 2 nr. fixing holes in the cill.	3	

Ref.	Elevation	Level	Condition: Head	Priority	Cost £	Condition: Cill	Priority	Cost £
W16	Front	First	There is a hairline crack to the head.	2		The cill has been repaired and decorated historically. There is a large crack, spanning through the centre of the cill vertically.	2	
W17	Front	First	Fair condition.	3		No cill.	3	
W18	Front	First	Fair condition.	3		The cill has been redecorated white. Previous repairs not visible.	3	
W19	Front	First	Fair condition.	3		Historically repaired and decorated. With some cracking evident	3	
W20	Front	First	Not observable because it is flush with the soffit.	3		Fair condition. Only with minor chipping.	3	
W21	Front	Second	Fair condition.	3		There has been an historic repair and decoration to this cill. The cill is showing signs of chipping	3	
W22	Front	Second	Fair condition.	3		No cill.	3	
W23	Front	Second	Fair condition.	2		The cill has been repaired historically. There are numerous cracks throughout the cill.	2	
W24	Front	Second	Fair condition.	3		Fair condition.	3	
W25	Front	Second	Fair condition.	3		No cill as it is the double door to the Juliet balcony.	3	
W26	Front	Second	Fair condition.	1		The cill has been repaired historically. There are numerous cracks throughout the cill.	1	
W27	Side	Ground	There is a hairline crack starting to appear.	3		There is a crack starting to form, which slightly wider than a hairline crack.	3	
W28	Side	Ground	There are some fissures starting to form.	2		There is a hairline crack starting to form, on the right-hand side of the cill.	2	
W29	Side	Ground	Fair condition.	3		There are 2 nr. hairline cracks to the bottom cill. Repointed recently, as the colour match looked different from the originals.	3	
W30	Side	Ground	There is a hairline crack to the head.	2		There is a crack starting to form.	2	
W31	Side	First	Fair condition.	2		There are some instances of small cracking, and chipping to the underside.	2	

Ref.	Elevation	Level	Condition: Head	Priority	Cost £	Condition: Cill	Priority	Cost £
W32	Side	First	Fair condition.	2		There are some instances of small cracking, and chipping to the underside.	2	
W33	Side	First	Generally fair condition, view of the start of a hairline crack is manifesting.	2		There is a hairline crack, and 2 nr. chips to the underside.	2	
W34	Side	Second	Fair condition.	3		Only slight hairline crack, and some chipping to the underside.	3	
W35	Side	Second	Fair condition.	3		The bottom cill has had historic localised repairs, and there is some chipping on the underside of the cill. The repairs are in good condition.	3	
W36	Rear	Ground	Located above rear entrance to flats. It is comprised of two clear sections, with the left-hand side section showing a hairline crack.	3		No cill.	3	
W37	Rear	Ground	There is some cracking to the head.	3		There are small localised cracks appearing on the cill.	3	
W38	Rear	Ground	There is cracking to the head, as well as staining to the head.	3		There are small hair line cracks to the bottom cill.	3	
W39	Rear	Ground	The head is in fair condition, however, the pointing to the head is in poor condition. Repointing will be required here.	2		No cill.	2	
W40	Rear	Ground	There is a hairline crack to the head.	3		There are some minor chips to the bottom cill.	3	
W41	Rear	Ground	There is a hairline crack to the head.	3		There are some hairline cracks forming, as well as some minor chipping.	3	
W42	Rear	Ground	The head is in fair condition, however, the pointing to the head is in poor condition. Repointing will be required here.	2		No cill.	2	
W43	Rear	Ground	There are been a large historic repair to the top of the head. The repair is in fair/poor condition, and is showing signs of cracking, and has been colour matched differently to the original stone.	1		There is a hairline crack to the cill.	1	
W44	Rear	Ground	There is a hairline crack to the head.	3		There is a hairline crack to the cill.	3	
W45	Rear	Ground	Fair condition.	3		Fair condition, with localised historic repairs.	3	

Ref.	Elevation	Level	Condition: Head	Priority	Cost £	Condition: Cill	Priority	Cost £
W46	Rear	First	Partly obscured by the soffit.	3		Fair condition, with localised repair evident.	3	
W47	Rear	First	Fair condition.	1		Poor condition, has been historically repaired. It is beginning to show a significant crack.	1	
W48	Rear	First	There is some cracking to the head.	2		Fair condition.	2	
W49	Rear	First	Fair condition.	3		No bottom cill.	3	
W50	Rear	First	Fair condition, slight hairline crack starting to form.	3		Fair condition, looks to have been historically repaired in localised areas.	3	
W51	Rear	First	There is a small crack starting to form to the head.	1		Historically repaired, in poor condition, with fairly large crack starting to appear.	1	
W52	Rear	First	Fair condition.	3		No cill.	3	
W53	Rear	First	Fair condition.	1		Appears to have been historically repaired. Large cracking forming on the left-hand side. Aswell as some chipping to the underside.	1	
W54	Rear	First	Fair condition.	3		Fair condition, has been repaired historically.	3	
W55	Rear	First	Fair condition. Entire head is visible.	3		Fair condition.	3	
W56	Rear	Second	There is some cracking to the head.	1		Historically repaired, but in poor condition. Large crack forming to its left-hand side.	1	
W57	Rear	Second	Fair condition.	3		No cill.	3	
W58	Rear	Second	Fair condition.	3		Has been previously repaired, in fair condition.	3	
W59	Rear	Second	Slight hairline crack forming to the right-hand side of the head.	1		Has been previously repaired, a large crack is starting to form to the left-hand side. There is also some chipping to the underside, and some other localised patch repairs evident.	1	
W60	Rear	Second	Fair condition.	3		Fair condition.	3	
W61	Rear	Second	There is a slight crack forming to the head.	1		Has been historically repaired. A large crack is forming to the left-hand side of the cill.	1	